



(Compatible with original centre stand.  
 In case there is one, it is necessary to  
 replace the original rubber fit on the centre stand  
 and replace it with the rubber cod.206267,  
 the nut 200298 and the spacer 206366 )

Spring and rubber  
 replacement kit  
 Cod.303949001R

Original cable



**WARNING**

-it is advisable to optimize the carburation by remapping  
 the stock ECU or by adopting an additional ECU unit.

**ART. 80011 SPARE PARTS**

**DUCATI MULTISTRADA 950/950S**  
 (compatible with original under cowl)

**(A) FITTING KIT cod. 3080011601R**